

5/25/93

## Explanation of Sampling Conditions For a Screening Site Inspection



The second onsite phase of a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) screening site inspection is the sampling visit. The B&V Waste Science and Technology Corp. (BVWST) sampling team needs approximately two days at your site to sample soil and/or water to be analyzed for the chemical compounds and metals regulated by U.S. Environmental Protection Agency (USEPA) under Comprehensive Environmental Response Compensation and Liability Act. The site owner receives a copy of the final Screening Site Inspection Report, which contains analytical results of site samples taken by the BVWST team. If you want portions of any samples taken by BVWST, we are responsible to provide them under the following conditions:

1. You supply your own sample containers, which must meet the USEPA Region V Analytical Operations Branch specifications. Write them at 77 West Jackson Boulevard, Chicago, Illinois 60604 for the specifications. In addition, you supply the iced coolers to transport the samples to your chosen laboratory for analysis.
2. Cost of analysis by your chosen laboratory must be paid by you.

During sampling, small quantities of excess soil and/or water are produced as well as small quantities of rinse water and detergent solution from sampling equipment decontamination. USEPA instructs us to return all produced soil and/or water to its point of origin and return the sampled area to original condition as much as possible. The rinse water will be poured into the suspected contaminated areas, as it is greatly reduced in contaminant concentration. The detergent solution will likewise be poured into the suspected contaminated areas, as the detergent used is biodegradable. In the unlikely event that the BVWST team must use a solvent to complete the decontamination of sampling equipment, this material must be stored temporarily on site in secure containers (which BVWST provides) until transport of these materials by a licensed hazardous waste hauler under proper manifesting is arranged to either a licensed treatment or disposal facility.

We send two Sampling Conditions Explanation copies. Please provide the information indicated below, sign one copy and give it to the BVWST Team Leader at the time of the reconnaissance and interview. Thank you for your cooperation.

As owner / operator (mark out inappropriate term) of the Henry Hoffman  
Landfill, CERCLIS ID No. ILD 984 791 657:

1. I want / do not want (mark out inappropriate term) a separate suite of samples taken by the BVWST Team, and
2. I agree to the temporary holding, if deemed necessary by BVWST, on the site of materials produced by the sampling procedures until their removal by a licensed hazardous waste hauler.

Signed Henry Hoffman  
Name printed Henry Hoffman  
Title Owner  
Date 5-25-93

SC-9/SSI G4

Is your RETURN ADDRESS completed on the reverse side?

**SENDER:**

- Complete item
- Complete item
- Print your name
- Attach this form
- Write "Return"
- The Return Recd

3. Article Address

Mr. H  
109  
Rock

5. Signature

6. Signature

PS Form 3800, June 1991

Postmark or Date		4.28.93	
Return Receipt Showing to Whom & Date Delivered	Return Receipt Showing to Whom, Date, and Addressee's Address	TOTAL Postage & Fees	Postage
		1.00	\$ .98
Restricted Delivery Fee			
Special Delivery Fee			
Certified Fee		1.00	
Sent to Special No. 109 Hoffman Drive Rock Falls, IL 61701			

**Receipt for Certified Mail**  
No Insurance Coverage Provided  
Do not use for International Mail  
(See Reverse)

PS Form 3811, December 1991 ☆ U.S.G.P.O. : 1992-307-530

**DOMESTIC RETURN RECEIPT**